

rev. 00 - 14/10/22

## PICO HP2

kit de réparation

ACZ500009 - ACZ500003 - ACZ500015  
 ACZ500019 - ACZ500021 - ACZ500011  
 ACZ500006 - ACZ500004 - ACZ500016  
 ACZ500018 - ACZ500020 - ACZ500022  
 ACZ500010 - ACZ500008 - ACZ500017  
 ACZ500013 - ACZ500007 - ACZ500005



### LE KIT CONTIENT:

- Partie avant esthétique
- Carte de gestion électronique
- 2 moteurs
- Bloc d'alimentation
- Câble de connexion

Le kit est livré pré-assemblé

### ARTICLES

CODE	DESCRIPTION
ACZ500009	
ACZ500003	
ACZ500015	
ACZ500019	
ACZ500021	
ACZ500011	
ACZ500006	
ACZ500004	
ACZ500016	
ACZ500018	
ACZ500020	
ACZ500022	
ACZ500010	
ACZ500008	
ACZ500017	
ACZ500013	
ACZ500007	
ACZ500005	